


FIG. 1






FIG. 3






FIG. 4



F I G . 5



F I G . 6




FIG. 7





FIG. 8



F I G . 9

PARAMETER DATA 1 0 4

	STRENGTH CONTROL PARAMETER	TIME CONTROL PARAMETER
RADIATION FEEDER 5 a	Pr 1a	Pr 2a
RADIATION FEEDER 5 b	Pr 1b	Pr 2b
RADIATION FEEDER 5 n	Pr 1n	Pr 2n